





**UTILISER UN CHIFFON OU DU TISSU
POUR PROTÉGER LES ÉCROUS
LORS DU SERRAGE**

**UTILIZAR UN PAÑO O TRAPO SUAVE
PARA PROTEGER LAS TUERCAS
DURANTE EL MONTAJE**



**USARE UN PANNINO O DEL TESSUTO
PER PROTEGGERE LE CALOTTE
DURANTE IL SERRAGGIO**

**USE SOFT CLOTH OR TISSUE
TO PROTECT UNION NUTS
WHEN TIGHTENING**





Pression dynamique minimum recommandée 1,5 bar
Nettoyer régulièrement les picots

Presión dinámica mínima de trabajo recomendada 1,5 bar
Limpiar regularmente las salidas de agua anti-cal

Pressione dinamica minima di utilizzo consigliata 1,5 bar
Pulire regolarmente gli ugelli

Minimum Dynamic Pressure Suggested 1,5 bar
clean the nozzles periodically

